



Win30 Vending Machine Reinvestment Sticker Instructions - For Installation To be completed with launch of HotWins™

Along with the upcoming launch of HotWins, the reinvestment amount available at Illinois Lottery vending machines is changing from \$100 to \$200. With this, there is a sticker change that needs to be made to the Illinois Lottery Win30 vending machines that retailers are responsible for. Please read all the instructions prior to attempting to replace the reinvestment sticker on the Win30 vending machine. If you have any questions, please contact the Retailer Hotline at (844) 806-8930. **Perform the replacement at a time when the vending machine will not be busy. See below for the Installation Instructions.**

Sticker Overview & Instructions:


New Reinvestment sticker - “To redeem winning tickets more than \$200 Please see Lottery Retailer”

- Step 1:** Slowly and carefully peel the new reinvestment sticker off the backing paper.
- Step 2:** Align the top of the new reinvestment sticker with the top of the current reinvestment sticker area on the Win30.
- Step 3:** Align the bottom of the new reinvestment sticker with the bottom of the current reinvestment sticker area on the Win30.
- Step 4:** Once you are confident you have accurately aligned the new reinvestment sticker, rub the surface of the new reinvestment sticker with the palm of your hand, using gentle but consistent force, to ensure that the sticker is properly secured.

Note: These are self-adhesive stickers, do not moisten.

Do not attempt to remove the old sticker.

*Do not attempt to peel off and reattach several times as dust and debris will attach to the adhesive. If you must peel it off, replace with a new sticker.



After Completed Replacement

As a reminder, pursuant to the IDL-61 Retailer Agreement for Sale of Lottery Tickets, the Illinois Department of Lottery and Allwyn Illinois LLC shall not be liable for any retailer's or retailer employee's failure to correctly place the reinvestment update stickers on a Win30 or DTS vending machine in a timely manner.